

## New Crusher:Shibang Crushers

### Shibang Crusher broken What are the mains way ?

Ore crushing and grinding method primarily with the role of institutions of the more common mechanical force generally have the following five. 1. Crushed by two broken face when approaching the squeeze pressure and make the materials broken. Impact crusher, [hammer crusher](#), [cone crusher](#) Crushing machines are the main mode of broken machinery. 2. Split broken teeth wedge tip is to use the materials to carry out the split of the broken, and the role of the concentration of a limited fragmentation, adapted to brittle Materials broken. 3. Broken materials in the face of crushing load as bear on the two points (or fulcrum) beam, the material itself in packs of breaking Whitty Broken. 4. Stripping two broken face grinding materials made in the relative movement of materials imposed shear stress, so that material rupture occurred. Of this fine-grained materials suitable for [grinding mill](#). 5. Crushing impact of the use of it is broken ore. Impact of the moment is the role of the ore. For example, the [impact crusher](#) is broken in the main impact .

[SBM Crusher](#)